

**From:** [raymond.melton@okc.gov](mailto:raymond.melton@okc.gov)  
**To:** [derek.johnson@okc.gov](mailto:derek.johnson@okc.gov); [clint.greenwood@okc.gov](mailto:clint.greenwood@okc.gov); [carl.cobb@okc.gov](mailto:carl.cobb@okc.gov); [Mark.Hildebrand@deg.ok.gov](mailto:Mark.Hildebrand@deg.ok.gov); [Jhana Enders/R6/USEPA/US@EPA](mailto:Jhana.Enders/R6/USEPA/US@EPA)  
**Cc:** [chayes@bachmanservices.com](mailto:chayes@bachmanservices.com)  
**Subject:** FW: Report  
**Date:** 07/31/2012 04:32 PM  
**Attachments:** [2012070471-c.pdf](#)  
[2012070471-q.pdf](#)  
[2012070471-r.pdf](#)

---

Bachman Sampling Results and comments.

**Raymond L. Melton, CSI, CPESC**

*Environmental Protection Manager  
City of Oklahoma City  
420 W. Main, 7th Floor  
Oklahoma City, OK. 73102  
405-297-2179*

---

**From:** Carla Hayes [mailto:[chayes@bachmanservices.com](mailto:chayes@bachmanservices.com)]  
**Sent:** Tuesday, July 31, 2012 4:08 PM  
**To:** Melton, Raymond L; Johnson, Derek T; [ecleanup@att.net](mailto:ecleanup@att.net)  
**Subject:** FW: Report

Raymond Melton,

Here are the results for the upper Canadian River outfall 1372 and results for frac tank #1617.

I would like for you to consider these few points:

- 1.The concentration of xylene for the frac tank equals 8.13 gallons for the 21,000 gallon container.
2. Xylene was not in the blend room at the time of the fire by our inventory records and is not stored in the blend room.  
Xylene is gravity fed from tanks located on the far east side of the plant to the blender room and put into a dedicated oil based tank or dedicated oil based vat once these are blended they are then drummed or placed in totes and then shipped out.
3. At the time of the incident the dedicated water based vat had 12 drums of product CSW 9013 that contains no xylene.  
Also at the time of the incident the dedicated water based tank had 20 drums of SCW 7526 that contains no xylene.
4. We can reconfirm this finding when we are able to vacuum the tanks out in the blend room.
5. The xylene analysis CAS #'s do not match the CAS# for the raw material we receive.
6. We don't know where the xylene came from because we can't account for it and we can account for everything else by our inventory records.

Please let me know what you think.



9531289

Thanks  
Carla Hayes  
Bachman Services, INC.

---

**From:** Russell Britten [mailto:RBritten@etilab.com]  
**Sent:** Tuesday, July 31, 2012 11:29 AM  
**To:** Carla Hayes  
**Subject:** Report

Thank You!

Russell Britten  
President  
Email logo



4619 N. Santa Fe Ave.  
Oklahoma City, OK 73118  
(405) 488-2400 Office  
(405) 990-3265 Cell  
(405) 488-2404 Fax  
[www.eti-lab.com](http://www.eti-lab.com)

---

**CONFIDENTIALITY NOTE:** This e-mail message and any attachments are intended solely for the person to which it is addressed and may contain privileged and confidential information protected by law. If you have received this communication in error, please notify the sender immediately by telephone or e-mail, destroy this message and delete any copies held in your electronic files. Unauthorized use and/or re-disclosure may subject you to penalties under applicable state and federal laws.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*